

Front Wiper Repair Kit, VW Golf IV, Audi A3, Seat, Skoda (Art. 8631)

**PRO+**

- for repairing rusted wiper arm shafts
- replacement of wiper arm mechanism is not required
- saves repair costs

Technical modifications reserved - we are not responsible for issues while printing